

# Oil Field Environmental Incident Summary

**Incident:** 20150307160712      **Date/Time of Notice:** 03/07/2015 16:07  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** MARY ANN 1-15H  
**Field Name:** JOHNSON CORNER      **Well File #:** 17323  
**Date Incident:** 3/6/2015      **Time Incident:** 21:00      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 96      **Sec:** 15      **Qtr:** NE NW  
**Location Description:** immediately adjacent to the south east side of the pad

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Cultivated      **Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.8 Mile  
**Distance Nearest Water Well:** 0.8 Mile

**Type of Incident** Other

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Reported to NRC:</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	11	Barrels			No		
<b>Brine</b>							
<b>Other</b>							

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**  
**Risk Evaluation:**  
none

**Areal Extent:**  
approximately 300 feet by 300 feet.

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Oil impacted soil and debris will be collected for appropriate disposal.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 3/9/2015

**Status:** Reviewed; Followup Required

**Staff:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Apparent spray off location. Cause not specified. Spray went off the SE side of the location. Followup is necessary.